

CERTIFICATE OF COMPLIANCE

Certificate Number 20161226-E484234
Report Reference E484234-20161226
Issue Date 2016-DECEMBER-26

Issued to: ZHEJIANG LIANXIANG HARDWARE SCIENCE AND TECHNOLOGY CO LTD
WEST SIDE OF QINSHAN RD
LUOTANG COUNTRY
QINSHAN ST
HAIYAN
ZHEJIANG 314300 CHINA

This is to certify that representative samples of

CONDUIT AND CABLE HARDWARE
Two Hole Steel Straps for CPVC, Cat. Nos. LX107, LX108, LX109 and LXS00, followed by 20, 25, 32, 40 or 50.

Beam Clamps, Cat. Nos.: BC006Z-0037, BC006Z-0050, BC006K-0037, BC006K-0050, AZ0037, AZ0050, AZ0062, AZ0075, AK0037, AK0050, AK0062, AK0075, BC002-1/4, BC002-3/8, BC002-1/2, BC007-M8, BC007-M10, BC007-M12.

Have been investigated by UL in accordance with the Standard(s) indicated on this Certificate.

Standard(s) for Safety: UL 2239 and CSA C22.2 No. 18.4-15, Hardware for the Support of Conduit, Tubing and Cable

Additional Information: See the UL Online Certifications Directory at www.ul.com/database for additional information

Only those products bearing the UL Certification Mark should be considered as being covered by UL's Certification and Follow-Up Service.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program
UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

